

FORM A

**REPORT OF INSPECTION IN ACCORDANCE WITH THE MEMORANDUM<sup>①</sup>  
OF UNDERSTANDING ON PORT STATE CONTROL IN THE ASIA-PACIFIC REGION**

Authority: MARITIME SAFETY ADMINISTRATION OF  
THE PEOPLE'S REPUBLIC OF CHINA  
Add: 11, Jianguomennei Ave. Beijing, 100736  
Tel: +86-10-6529-2872  
Fax: +86-10-6529-2875  
Cable: MINOCOM  
Telex: 222258 CMSAR CN  
E-mail: china\_psc@msa.gov.cn

Copy to: Master  
Head office  
PSCO  
If ship is detained, copy to:  
Flag State  
IMO  
Recognize organization, if applicable

1 name of reporting authority CHINA MSA 2 name of ship LMZ ATLAS  
3 flag of ship CY-Cyprus 4 type of ship 340-Bulk carrier 5a Call Sign 5BHB5 5b MMSI number 209669000  
6 IMO number 9850018 7 gross tonnage 44114 8 deadweight(when applicable) 81800  
9 date of keel laid 18.12.2015 10 date of inspection 16.05.2023 11 place of inspection Rizhao  
12 classification society 115-Bureau Veritas 13 date of release from detention ②  
14a IMO company number 1848703 14b particulars of company (DOC) LMZ Shipping SA

15 name and signature of master to certify that the information under 14 is correct  
Name ESTRELLA IVANHOE JESUS ROMAN LAUREL Signature

## 16 details of ship certificates

a title	b issuing authority	c date of issue	and expiry
1) 501-Cargo Ship Safety Construction (including Exemption)	Bureau Veritas	03.11.2020	09.09.2024
2) 502-Cargo Ship Safety Equipment (including Exemption)	Bureau Veritas	02.08.2022	09.09.2024
3) 503-Cargo Ship Safety Radio (including Exemption)	Bureau Veritas	02.08.2022	09.09.2024
4) 505-Prevention of Pollution by Oil(IOPP)	Bureau Veritas	03.11.2020	09.09.2024
5) 506-International Air Pollution Prevention Certificate(IAPP)	Bureau Veritas	02.08.2022	09.09.2024
6) 507-International Sewage Pollution Prevention Certificate	Bureau Veritas	03.11.2020	09.09.2024
7) 508-Load Lines	Bureau Veritas	02.08.2022	09.09.2024
8) 509-Document of Compliance ( DoC/ISM Code )	Bureau Veritas	20.04.2019	06.05.2024
9) 510-Safety Management Certificate	Bureau Veritas	11.03.2023	07.03.2025
10) 511-International Ship Security Certificate	Bureau Veritas	11.03.2023	07.03.2025
11) 512-Minimum Safety Manning Document	Cyprus	03.01.2020	09.09.2024
12) 523-Tonnage	Bureau Veritas	19.07.2019	
13) 528-International Ballast Water Management	Bureau Veritas	02.08.2022	09.09.2024
14) 529-International Anti-fouling-System Certificate ( IAFSC )	Bureau Veritas	03.11.2020	
15) 532-International Energy Efficiency(IEE)	Bureau Veritas	03.11.2020	
16) 533-Maritime Labour Certificate	Bureau Veritas	14.07.2020	07.03.2025

## d information on last intermediate or annual survey

Date(DD.MM.YYYY)	Surveying authority	Place
1) 02.08.2022	115-Bureau Veritas	SILLAMAE
2)		
3)		
4) 02.08.2022	115-Bureau Veritas	SILLAMAE
5)		
6)		
7)		
8) 29.07.2022	115-Bureau Veritas	SILLAMAE
9)		
10)		
11)		
12)		
13)		
14)		
15)		
16)		

## 17 deficiencies

## 18 ship detained

## 19 supporting documentation

☐ no ☐ yes(see attached FORM B)  
☐ no ☐ yes ③  
☐ no ☐ yes(see annex)

## issuing

## office:

Rizhao MSA (5)

Telephone: +86-0633-7989567

Telefax: +86-0633-8385428

E-mail: lsm@msa.gov.cn

Name: LIU XIQING, YANG SHIBIN

(duly authorized PSCO of reporting authority)

Signature:

This report must be retained on board for period of two years and must be available for consultation by Port State Control Officers at all times.

① This inspection report has been issued solely for the purpose of informing the master and other port State that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.

② To be completed in the event of a detention.

③ Masters and companies are advised that detailed information on a detention may be subject to future publication.

FORM B

# REPORT OF INSPECTION IN ACCORDANCE WITH THE MEMORANDUM<sup>④</sup> OF UNDERSTANDING ON PORT STATE CONTROL IN THE ASIA-PACIFIC REGION


Authority: MARITIME SAFETY ADMINISTRATION OF  
THE PEOPLE'S REPUBLIC OF CHINA  
Add: 11, Jianguomennei Ave. Beijing, 100736  
Tel: +86-10-6529-2872  
Fax: +86-10-6529-2875  
Cable: MINOCOM  
Telex: 222258 CMSAR CN  
E-mail: china\_psc@msa.gov.cn

Copy to: Master  
Head office  
PSCO  
If ship is detained, copy to:  
Flag State  
IMO  
Recognize organization, if applicable

2 name of ship: LMZ ATLAS  
10 date of inspection: 16.05.2023

6 IMO number: 9850018  
11 place of inspection: Rizhao

20 No.	21 code	nature of deficiency <sup>④</sup>	convention reference <sup>⑤</sup>	22 action taken <sup>⑥</sup>	23 responsible RO <sup>⑤</sup>	24 ISM related
1	07116	THE VENT OF GALLY ROOM DIFFICULT TO CLOSE	—	17/10 5		<input type="checkbox"/>
2	09219	INSULATION OF 220V ON EMERGENCY SWITCH BOARD TOO LOW	—	17/10 5		<input type="checkbox"/>
3	09203	ONE LIGHT BESIDE EMERGENCY GENERATOR ROOM OUT OF ORDER	—	17/10 5		<input type="checkbox"/>
4	03103	THE HEIGHT OF GUARD CHAIN BESIDE P&S GANGWAY LESS THAN 1 METER	—	17/10 5		<input type="checkbox"/>
5	09130	HANDLE WHEEL OF VALVE ON FRESH WATER PIPE BESIDE STARBOARD GANGWAY BROKEN	—	17/10 5		<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>
—	—	—	—	—	—	<input type="checkbox"/>



Name: LIU XIQING, YANG SHIBIN  
(duly authorized PSCO of reporting authority)

Signature: 

<sup>④</sup> This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that full survey is carried out and all deficiencies are rectified before an application for re-inspection is made.

<sup>⑤</sup> To be completed in the event of a detention.

<sup>⑥</sup> Applicable Deficiency Action Codes (see reverse side of copy) to be entered.