

**Hanzevast Shipmanagement BV****HVSM.215****MATERIAL LANDING RECEIPT****Vessel: M/V HANZE GENDT****Receipt No. 014/2023****Date Landed: 26 July 2023****Port Landed: Rio Grande, Brazil****Item Description and Landing Reasons:**

DHL plastic bag containing 1 (one) fuel samples bunkered in p. Rio Grande, Brazil for analyses;  
1 (one) pc. VLSFO sample bottle

1. Instructions to Vendor: Vendor to notify Technical Department via E-mail or fax immediately upon receipt of materials. An estimate for repair should be sent to HVSM and a purchase order number received prior to repair.

Address: Technical Department (HVSM) and Superintendent at respective mail ID

Contact: Hanzevast Shipmanagement BV

- Email: [bulktechnical@hanzevastshipping.nl](mailto:bulktechnical@hanzevastshipping.nl) , [JEijkelenborg@hanzevast.nl](mailto:JEijkelenborg@hanzevast.nl) ,  
[chief.gendt@hanzefleet.com](mailto:chief.gendt@hanzefleet.com)

- Tel: + 31 613 989 627

2. Vendor Reply: Vendor must prepare service report (which must include name / quantity of parts scrapped after repair) and attach a copy to this Landing Receipt. These documents to be sent along with item/s being returned to the vessel, with copy to HVSM

**F.O. SAMPLES: DHL Airway bill no.: 2152862515**

Ship to: Viswalab Houston


12140 Almeda Rd,  
Houston, TX77045, USA

FAX: +1 (173) 842 1981

E-mail: [customerhelp@theviswagroup.com](mailto:customerhelp@theviswagroup.com)

Receiver acknowledges the receipt and responsibility for the above listed materials.

Godovanyuk, Mykola  
Chief Engineer



Receiver/  
Receiver's Company:

SOCIRADE

Receiver's Name (printed)

FELIPE FERRGIRA

**VESSEL INSTRUCTIONS:** This form must be used whenever any item is landed from the vessel.

Distribution: One copy goes with item landed. Second copy to be forwarded via mail to Technical Department. Third copy remains onboard and filed in CE file # 3.

Rev Date: Nov 2010

Prep: DPA

Appr: MD

Ver: 1

Rev: 0

Page 1 of 1